
Exisiting Facade
Exisiting Facade
Exisiting Facade
Exisiting Facade
Exisiting Facade
Exisiting Facade
Exisiting Facade
Exisiting Facade
Exisiting Facade
Exisiting Facade
Exisiting Facade
Exisiting Facade
Exit
Entry
DN
Slope 10%
Slope 18%
Slope 10%
Slope 18%
Female Prayer 226
Female Ablution 227
Male Prayer 228
Ablution 229
Female Public toilets 225
Lobby 259
Male Public toilets 250
Lobby 258
Corridor 208
Accounting Office 234
Janitor 235
Male Staff Toilet 236
Lobby 261
Male Staff Lounge 233
Female Staff Lounge 232
Unit S/S 263
Store 238
Meter Room 264
Medical Records 239
Electricity Room 240
Female Staff Lounge 260
Existing
Existing
Existing